



District Management

Assistant DE (North)Ed Wilson	
Assistant DE (South)	
Development EngineerVacant	
Senior RE Show LowRandy Routhier	-
Senior RE HolbrookCarl Ericksen	
Resident Engineer	

ADOT Engineering and Maintenance District Northeast



Completed Projects



Burnside Jct-Ganado, Phase 3 of 3

- *HSIP (safety)funding
- *Pavement Preservation funding
- *Bridge replacement funding



















City Of Show Low, local Government project




Recently completed Projects




Recent and Current Projects



Recent and Current Projects




2018 Projects




ADOT Engineering and Maintenance District Northeast

2019-2021 **Pavement Projects**



ADOT Engineering and Maintenance District Northeast

2019-2021 Bridge Projects



Safety Improvement study Chinle To Many Farms US 191 MP 440-470



US 191 Chinle to Many Farms Safety Improvement Study MPD Task Assignment 0026-17

PREVIOUSLY IDENTIFIED ISSUES/OPPORTUNITIES

Roadway Characteristics

Many Farms Area

Safety

 Vehicle, pedestrian, and student safety concerns at the intersection of N-59 & U.S. 191.

Traffic Control

- Provide a traffic signal or a roundabout at the intersection of U.S. 191
 N59
- · Eastbound backups may require turn lanes.

Safety

. Need for cattle guard.

Capacity

Poor Level of Service (LOS)

Speeding

- . Install solar speed monitors. Coordinate with a speed study.
- Evaluate use of photo radar enforcement in Many Farms.
- Conduct speed studies to determine appropriate speed limits.

Widening/Capacity

 Replace/widen Black Mountain Wash Bridge (MP 460.26).

Access

 Residents have created an informal frontage road for access to adjacent property.

NISOST

- . Connects back road to Many Farms (N8084)
- · Frequent access to private property.

Horizontal Curve Delineation (4 locations)

- Delineate horizontal curves with flexible delineators, chevrons, and curve. warning signs as appropriate.
- Evaluate need for Southbound passing lane and/or deceleration lane near MP 454 (no passing Southbound).



Additional Comments

Please add any additional comments, and draw any diagrams here or on the map where they occur to show additional ROADWAY CHARACTERISTICS issues not already reflected on this poster.

I-40 at Joseph City flooding Last night



